

HABS
ID,
11-EAPO,
1-B-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS No. ID-101-B

United States Border Inspection Station , Immigration Officers Residence
West Side of U.S. Route 95
Eastport
Boundary County
Idaho

Harvey S. Rice, Photographer June 1988

United States Border Inspection Station, Immigration Officers Residence

EXTERIOR PHOTOGRAPHS

ID-101-B-1 NORTH AND EAST ELEVATIONS, VIEW TO SOUTHWEST

ID-101-B-2 NORTH ELEVATION, VIEW TO SOUTH

HISTORIC VIEW

ID-101-B-3 Photocopy of a photograph (from the General Services Administration, Auburn, Washington)
Photographer unknown, November 1962
IMMIGRATION RESIDENCE PRIOR TO ALTERATION OF THE PORCH STAIRS
AND INSTALLATION OF SCREENS ON THE FRONT PORCH, VIEW TO THE
SOUTHWEST